


8

HORIZONTAL - SQUARE STOPS

SEE "MUNTIN OPTIONS"
FOR ADDITIONAL CONFIGURATIONS



NOTE: GLAZING BEADS MUST BE NOTCHED AT SETTING BLOCKS

